


FRONT VIEW



Note 1: Transition to 3.125 EIA Flange must be removable and capable of outputting to either side of the magnetron.